

Work Permit # DRL-2008-9
Work Order # _____
Job# ____ Activity# ____

Work requester fills out this section.	☐ Standing Work Permit										
Requester: Don Lynch	Date: 10/21/2008	Ext.: 2253	Dept/Div/Group: PO/PHENIX								
Other Contact person (if different from re	requester): Carter Biggs		Ext.: 7515	Ext.: 7515							
Work Control Coordinator: Don Lynch		Start Date: 10/20/2008 Est. End Date: 2/1/09									
Brief Description of Work: Install RPC2	ief Description of Work: Install RPC2 Prototype										
Building: 1008	Room: IR	Equipment: RPC	Service Provider: PHEN	IX techs & RPC experts							
CC, Requester/Designee, Service Provider, and ES&H (as necessary) fill out this section or attach analysis											
ES&H ANALYSIS	ES&H ANALYSIS										
	None	Airborne	Contamination	Radiation							
	•	, ,	Soil Density Gauges								
☐ Special nuclear materials involved	d, notify Isotope Special Materials Gro		Fissionable materials involv	als involved, notify Laboratory Criticality Officer							
Safety Concerns	None None	☐ Ergonomics	☐ Transport of Haz/Rad Mater								
☐ Adding/Removing Walls or Roofs	☐ Confined Space*	☐ Explosives	☐ Lead*	Penetrating Fire Walls							
_	☐ Corrosive	☐ Flammable	☐ Magnetic Field*	☐ Pressurized Systems							
Asbestos*	Cryogenic	Fumes/Mist/Dust*	Material Handling	Rigging/Critical Lift							
Beryllium*	☐ Electrical	Heat/Cold Stress	☐ Noise*	Toxic Materials*							
☐ Biohazard*		Hydraulic	Non-ionizing Radiation*	☐ Vacuum							
☐ Chemicals*	☐ Excavation	Lasers*	Oxygen Deficiency* Other								
* Does this work require medical clears	ance or surveillance from the Occupa										
Environmental Concerns		None	Work impacts Environmental Permit No.								
Atmospheric Discharges (rad/non-	<u>'</u>	☐ Land Use	Soil Activation/contamination	☐ Waste-Mixed							
☐ Chemical or Rad Material Storage	e or Use	Liquid Discharges	☐ Waste-Clean	☐ Waste-Radioactive							
☐ Cesspools (UIC)		☐ Oil/PCB Management	☐ Waste-Hazardous	☐ Waste-Regulated Medical							
☐ High water/power consumption		☐ Spill potential	☐ Waste-Industrial	☐ Underground Duct/Piping							
Waste disposition by:				☐ Other							
Pollution Prevention (P2)/Waste Min	nimization Opportunity:	None ☐ Yes	e 🔲 Yes								
FACILITY CONCERNS	None Non										
Access/Egress Limitations	☐ Electrical Noise	☐ Potential to Cause a F		☐ Vibrations							
	Impacts Facility Use Agre		Temperature Change	Other							
Configuration Control	☐ Maintenance Work on Ve	ntilation Systems	Utility Interruptions								
	WORK CONTROLS										
Work Practices	Exhaust Ventilation		Spill Containment	Converte (one Instruction Cheet)							
None		Posting/Warning	<u> </u>	Security (see Instruction Sheet)							
■ Back-up Person/Watch ■ Back-up Pe	☐ HP Coverage	Signs Scaffolding-requires	☐ Time Limitation	☐ Other							
Barricades	☐ IH Survey	inspection	☐ Warning Alarm (i.e. "high level")								
Protective Equipment		□ Gloves									
None	☐ Ear Plugs		Lab Coat	Safety Glasses							
Coveralls	-		Respirator	Safety Harness							
☐ Disposable Clothing	☐ Face Shield	Hard Hat	☐ Shoe Covers	Shoes Other							
Permits Required (Permits must be v		T =									
None	Cutting/Welding	Impair Fire Protection	-								
Concrete/Masonry Penetration	☐ Digging/Core Drilling	Rad Work Permit-RWF	2 NO								
Confined Space Entry	☐ Electrical Working Hot	☐ Other									
Dosimetry/Monitoring None	☐ Heat Stress Monitor	Real Time Monitor	TLD								
☐ Air Effluent	☐ Noise Survey/Dosimeter	☐ Self-reading Pencil	Waste Characterization								
Ground Water	☐ O₂/Combustible Gas	Dosimeter Self-reading Digital	Other Check O2 level prior to entry								
_		Dosimeter Sorbent Tube/Filter	La Culci Olicek Oz level pilot to entry								
Liquid Effluent	☐ Passive Vapor Monitor	Pump									
Training Requirements (List below specific training requirements)											
Confined Space, CA -Collider User, PHENIX Awareness											
Based on analysis above, the Walko ratings below:	down Team determines the risk, co	mplexity, and coordination	If using the permit when all hazard ratings are low, only the following need to sign: (Although allowed, there is no need to use back of form)								
ES&H Risk Level:		High	WCC:	Date:							
Complexity Level:		☐ High	Service Provider:	Date:							
Work Coordination:		☐ High	Authorization to start	Date:							
				.							

	Work Plan (procedures, timing, equipment, and personnel availability need to be addressed): See Attached Work Plan										
	Special Working Conditions Required: None										
	Operational Limits Imposed: Modification work limited to lower octants easily reachable when standing on lower magnet superstructure.										
	Post Work Testing Required: No										
	Job Safety Analysis Required: ☐ Yes		Walkdown Required: ☑ Yes ☐ No								
	<u> </u>										
	Reviewed by: Primary Reviewer will determine the size of the review team and the other signatures required based on hazards and job complexity. Primary Reviewer signature mea hat the hazards and risks that could impact ES&H have been identified and will be controlled according to BNL requirements.										
	<u>Title</u>			(print) Signature		Life #		<u>Date</u>			
	Primary Reviewer										
	ES&H Professional										
	Other										
	Other										
	Work Control Coordinator										
	Service Provider										
		Review	v Done: in series	☐ team							
ļ		TOVION	Pone. In series	Liteam							
4. Joh	site personnel fill out this section.										
	Note: Signature indicates personnel performing work have read and understand the hazards and permit requirements (including any attachments).										
	Job Supervisor:	Supervisor:			Contractor Supervisor:						
	Workers:		Life#:		Workers: Life#		Life#:	<i>‡</i> :			
	Workers are encouraged to provide feed	lback on I	ES&H concerns or on idea	as for improved job	work flow. Use f	eedback form or space be	low.				
5. De	partmental Job Supervisor, Work Contr	ol Coord	inator/Designee								
	Conditions are appropriate to start work:			controls are in plac	ce and site is read	ly for job.)					
	Name:	ame: Signature:			Life#:			Date:			
6. Dei	partmental Job Supervisor, Work Requ	ester/Des	signee determines if Pos	t Job Review is r	eauired. Nes	s 🗆 No					
	Post Job Review (Fill in names of review		- J								
	lame: Signature:				Life#:		Date:				
	Name: Signature:		Life#:		Date:		:				
I											
7. Wo	rker provides feedback. Worker Feedback (use attached sheets	as nacas	ean/l								
	Worker Feedback (use attached sheets as necessary) a) WCM/WCC: Is any feedback required? ☐ Yes ☐ No										
	b) Workers: Are there better methods or safer ways to perform this job in the future? Yes No										
8. Clo	8. Closeout: Work Control Coordinator (authorizing dept.) checks quality of completed permit and ensures the work site is left in an acceptable condition. (WCC can delegate										
	up of work area to work supervisor)	<u> </u>	Γ				1	,			
	Name:		Signature:		Life#:		Date:				
	Comments:										

RPC2 Prototype Installation

Introduction

As a part of the PHENIX Muon Trigger Upgrade, 2 prototype detectors are to be installed in the PHENIX experiment complex. The first prototype (RPC2) will be installed on the north side of the south MuID detector in the PHENIX IR. The other prototype (RPC3) will be installed in the RHIC tunnel (sector 7) on the south side of the south MuID detector. This procedure is for the RPC2 prototype only, RPC3 will be installed by CAD personnel in accordance with a separate and distinct work plan.

The purpose of the prototype test is to assess the ability of the RPC design in the PHENIX experiment ambient conditions as well as to test the electronics, and the customized detector gas environment in the rigors of an experimental run.

Work Plan

This work is to be done by fully trained and experienced personnel (PHENIX mechanical and electrical technicians and RPC expert scientists) during the 2008 summer shutdown. All persons participating in the installation shall have current PHENIX Awareness and CA access. In addition, technicians participating in the installation shall have appropriate crane training, working at height training, manlift operation and/or electrical safety training as appropriate for the tasks being performed.

1. Preparation for installation

- RPC experts shall assemble and test the prototype in the RPC factory and have the prototype ready for installation when required by PHENIX technicians.
- Survey and prepare mounting points to suspend the RPC2 from (see figure 1).
- Load test suspension fixtures (wire rope, terminators) to certify the equipment for this application. And mount the fixtures with the wire rope hanging in their approximate final resting position.
- Prepare slings to orient RPC2 during installation. (See figure 2 for center of gravity info).

2. Prototype Transportation

-PHENIX techs shall arrange with BNL trades to have the prototype transported from the RPC factory to the PHENIX Assembly Hall (AH). Care shall be taken to assure that the

prototype is not jostled or otherwise mishandled during transport.

3. Installation

- Carefully lift the RPC2 in the AH using the slings prepared in step 1.
- -Move RPC2 around the East Carriage (EC) in the AH using the AH crane and set the RPC2 down on the 12 ton cart for transport into the Interaction Region (IR).
- -Once in the IR re-rig the RPC2 with the IR crane and slowly lift and move the prototype to its installed position.
- -Attach the suspension wires to the swivel hooks provided and slowly transfer the load from the crane/slings to the suspension wires.
- Disconnect the slings and move the slings/crane away from the RPC2.
- -Adjust the wires using the provided turnbuckles to level and position the RPC2 prototype as close as possible to its nominal installed position. Use the lower adjustment rods to remove any roll and yaw.
- -After the RPC2 is installed, survey the 10 marked bolt heads and provide the survey info to RPC experts.
- -Document all issues and problems encountered on the work permit.




Figure 1A: Prototype lifting & installation scheme (PHENIX Drawing # PHENIX-E-0050)




Figure 1B: RPC2 Prototype suspension scheme (PHENIX Drawing #105-0223-111C)




Figure 2: Prototype RPC2 Center of Gravity (PHENIX Drawing #105-0223-112D